

TOP SECRET

OUT56709

TOP SECRET 162208Z

1965 SEP 16 22 16Z

25X1

5467

OXCART

ATTENTION:

25X1

1. REQUEST COMPLETE TEST MISSION ON 116-A CAMERA SYSTEM UTILIZING PROCEDURES ESTABLISHED IN [] REPORTS MANUAL. [] WILL RUN TRIAL READOUT.

25X1

2. REQUEST FLIGHT LINE COVERAGE OVER "GREEN STAMP" AREAS WITH FOLLOWING CONDITIONS:

A. CATEGORY II OR BETTER WEATHER.

B. ALTITUDE TO BE IN EXCESS OF FL-700. AIRSPEED TO BE IN EXCESS OF M2.5.

C. LEVEL FLIGHT CONDITIONS WITH PACKAGE UNCAGED.

D. INS RECORDER TO BE IN OPERATION.

3. REQUEST FILM BE PROCESSED AT [] FURNISH TO [] ORIGINAL NEGATIVE AND TWO DUPLICATE POSITIVES. TITLE ACCORDING TO INSTRUCTIONS FURNISHED [] WILL ASSIST [] IN TITLING AND PREPARATION OF FILM EVALUATION REPORT [] 122).

4. FURNISH [] INS TAPE VIA 1004 NETWORK. INS MISSION NUMBER MUST AGREE WITH FILM MISSION NUMBER OR VICE VERSA.

5. FURNISH CALIBRATED FOLCAL LENGTH OF THE LENS MOUNTED IN EACH CAMERA.

TOP SECRET

--END OF MESSAGE--

17 SEP 1965

COPIES	1	Act.
IN		
BR		
DS		
SD	25X1	
PD		
PSD	25X1	
PSD-ICB		
TID	25X1	
PID		
PAG		
DIAXX 4		
SPAD		
NSA-LO		
DIA-AP		

25X1

TOP SECRET